

WELL INSPECTION

CLIENT'S NAME: Danielle and Andrew Standish

PROPERTY ADDRESS: 9708 S. Birchwood Drive, Baldwin, MI 49304

Date: 8-3-21

Time: 2:00 pm

Location of the well: **In well pit rear (East) of home in yard.**

Is the pump submerged in casing? Yes No

Size and Type: **2 inch steel case well.**

Location and condition of the pump and/or tank: **Both in well pit – Serviceable for size and type.**

Water pressure at the time of the inspection was: 50 pounds per square inch.

Does the pump cycle properly? Yes No

The limit switch comes on at 30 psi Goes off at 50 psi

Is the well at least 50 feet from the septic? Yes No

Is the well at least 75 feet from the drain field? Yes No

Is the well at least 10 feet from the property line? Yes No

Overall condition of the well and equipment: **Serviceable at the time of the inspection.**

This is an inspection of the well. It is neither a "Code Compliance" inspection nor a "Manufacturers Specifications" for installation, operation or repairs. The inspector can only inspect what he can see. If the water supply is provided by a well, only the above ground equipment is reviewed due to the inaccessible nature of the system. Sub-surface or concealed components are not within the scope of this report. This does not constitute a warranty or guarantee.

Top Quality Home Inspections

David C. Sillman, Inspector

Derek C. Hickey, Inspector

#0397995231